



JX6-SB(-I)

Version Update

from V 2.21 to V 2.22



Revision 1.02

Jetter AG reserves the right to make alterations to its products in the interest of technical progress. These alterations need not be documented in every single case.

This Version Update and the information contained herein have been compiled with due diligence. However, Jetter AG assume no liability for printing or other errors or damages arising from such errors.

The brand names and product names used in this document are trademarks or registered trademarks of the respective title owner.

Table of Contents

1	Introduction	4
	Operating System Update.....	5
	Overview of Version Updates.....	6
2	Fixed Software Bugs	7
	Monitoring Frames from CANopen Modules	8
	Module Codes of Festo CPX with CP Interface	9
	Initialization of the JX2 System Bus with LioN-S / LJX7-CSL Modules	10

1 Introduction

Introduction

This chapter shows the history of the JX6-SB(-I) module's operating system versions.

Operating System Update - Why?

An OS update allows you to:

- Expanding the function range
 - Fixing software bugs
 - Transmitting a certain operating system version, for example at releasing a customer-specific operating system version
-

Contents

Topic	Page
Operating System Update.....	5
Overview of Version Updates	6

Operating System Update

OS File for Operating System Update

For an operating system update, you will need the following file:

OS File	Description
JX6-SB(-I)_2.22.0.00.os	Operating system file for JX6-SB(-I) mit der Version 2.22.0.00.

OS File Download

Jetter AG make operating system files available for download from their **homepage at** <http://www.jetter.de>. OS files can be found via quicklink on the support site of the JX6-SB(-I) module.

Operating System Update by means of JetSym

To update your OS proceed as follows:

Step	Action
1	OS File Download from www.jetter.de
2	Establishing a connection between PC and controller
3	Executing the menu item Build > Operating System Update in JetSym
4	Selecting the OS File
5	Depending on the controller and on the module, the following items are to be specified: <ul style="list-style-type: none"> ▪ Module number ▪ Submodule socket ▪ Slave number ▪ I/O module number
6	Start the operating system update by ok
7	Result: After Power Off / Power On, the new operating system starts.

Overview of Version Updates

V 2.21

Function	New	Bug
Festo CPX Terminal:		
Support for CPX-CPI interface	✓	
BWU1821:		
Communication via command interface		✓
Read/write access from/to analog IOs		✓
CAN-PRIM:		
User programmable CAN-PRIM interface	✓	
LioN-S:		
Commissioning		✓

V 2.22

Function	New	Bug
Festo CPX terminal with CPX-CP interface:		
Module codes in module array and access to registers		✓
Monitoring frames to CANopen modules:		
Configuration of monitoring interval		✓
Initialization with LioN-S / LJX7-CSL modules:		
Detection of modules connected to the JX2 system bus		✓

2 Fixed Software Bugs

Introduction

This chapter describes the software bugs which have been fixed in the new operating system release.

Contents

Topic	Page
Monitoring Frames from CANopen Modules	8
Module Codes of Festo CPX with CP Interface	9
Initialization of the JX2 System Bus with LioN-S / LJX7-CSL Modules.....	10

Monitoring Frames from CANopen Modules

Effects of this Bug

The submodule or the controller does not send the monitoring frames to CANopen® modules within the configured time interval. The time interval is configured in register 2028 of the controller or register 3m02028 of JX6-SB(-I) modules.

If only one or a few CANopen® modules are connected to the JX2 system bus, the following effects may result:

- The CANopen® module is no longer ready for operation.
- The submodule or the controller is not able to read input data from the CANopen® module.
- The submodule or the controller is not able to write output data to the CANopen® module.

Affected Versions/Revisions

The following versions/revisions are affected by this bug:

OS version	JX6-SB(-I): 2.21.0.00 JC-24x: 3.26.0.00
Hardware revision	not applicable
Configuration or operating mode	not applicable
Note	760

Remedy / Workaround

Assign module number 79 to the CANopen® module. To do so, the node ID of the CANopen® module has to be changed.

Bug Fix

Starting from the following versions/revisions this bug has been fixed:

OS version	JX6-SB(-I): 2.22.0.00 JC-24x: 3.27.0.00
Hardware revision	not applicable
Configuration or operating mode	not applicable

Module Codes of Festo CPX with CP Interface

Effects of this Bug

When a CPX-CP interface is connected to a CPX terminal, the submodule or the controller creates a virtual CPX-FB14. The module codes of the CPX-FB14 and the virtual CPX-FB14 in the module array are interchanged. Registers 7xzz of the controller or registers 3m07xzz of the JX6-SB(-I) module cannot be accessed.

Affected Versions/Revisions

The following versions/revisions are affected by this bug:

OS version	JX6-SB(-I): 2.21.0.00 JC-24x: 3.26.0.00
Hardware revision	not applicable
Configuration or operating mode	not applicable
Note	894

Remedy / Workaround

There is no remedy for affected versions/revisions.

Bug Fix

Starting from the following versions/revisions this bug has been fixed:

OS version	JX6-SB(-I): 2.22.0.00 JC-24x: 3.27.0.00
Hardware revision	not applicable
Configuration or operating mode	not applicable

Initialization of the JX2 System Bus with LioN-S / LJX7-CSL Modules

Effects of this Bug

At baud rates other than 1 MBaud the controller or the submodule does not always detect all modules on the JX2 system bus if LioN-S or LJX7-CSL modules are connected.

Affected Versions/Revisions

The following versions/revisions are affected by this bug:

OS version	JX6-SB(-I): < 2.22.0.00 JC-24x: < 3.27
Hardware revision	not applicable
Configuration or operating mode	LioN-S modules or LJX7-CSL modules are connected to the JX2 system bus
Note	914

Remedy / Workaround

There is no remedy for affected versions/revisions.

Bug Fix

Starting from the following versions/revisions this bug has been fixed:

OS version	JX6-SB(-I): 2.22.0.00 JC-24x: 3.27
Hardware revision	not applicable
Configuration or operating mode	not applicable
