



JX2-SM2

Version Update

from V. 1.14 to V. 1.17



Jetter AG reserves the right to make alterations to its products in the interest of technical progress. These alterations need not be documented in every single case.

This user information and the information contained herein have been compiled with due diligence. However, Jetter AG assume no liability for printing or other errors or damages arising from such errors.

The brand names and product names used in this document are trademarks or registered trademarks of the respective title owner.

Contents

1	Introduction	4
2	Expansions	5
3	Fixed Software Bugs	6
3.1	Endless Run	6

1 Introduction

Overview of Version Updates			
Version	Description	upgraded	corrected
V. 1.17	Endless run stops unexpectedly		✓

2 Expansions

3 Fixed Software Bugs

3.1 Endless Run

Endless run stops unexpectedly

Any endless run (started by command 56 or 57), would in fact not be endless but stop by itself after 4,294,967,265 steps.

This was due to a firmware error, which has been fixed in version 1.17.