



JX3-COM-EIPA

Hardware revision update from rev. 00.02 to rev. 00.03

We automate your success.

Introduction

New hardware revision 00.03 of the JX3-COM-EIPA Hardware revision 00.03 of the JX3-COM-EIPA is completely compatible with the previous hardware revisions of the JX3-COM-EIPA.

Version 1.00

April 2015 / Printed in Germany

This document has been compiled by Jetter AG with due diligence, and based on the known state of the art.

In the case of modifications, further developments or enhancements to products shipped in the past, a revised document will be supplied only if required by law, or deemed appropriate by Jetter AG. Jetter AG shall neither be liable nor responsible for any errors in form or content, lacks in updating and possibly resulting damages or disadvantages.

The logos, brand names, and product names mentioned in this document are trademarks of Jetter AG, of associated companies or other title owners and must not be used without consent of the respective title owner.

Table of contents

1	Introduction	4
2	Changes made in hardware revision 00.03	5

1 Introduction

Overview
HW revision 00.03

The following table gives an overview of newly added or enhanced features and fixed software bugs:

Description	New	Enhanced	Fixed
New hardware revision 00.03	✓		

2 Changes made in hardware revision 00.03

Compatibility

Hardware revision 00.03 is completely compatible with the previous hardware revisions 00.01 and 00.02.

Hardware revision 00.01 needs at least

- min. boot loader version 9.01.0.00
- min. OS version 1.02.0.00

Hardware revisions 00.02 and 00.03 need at least

- min. boot loader version 9.01.0.00
 - min. OS version 1.05.0.00
-

Jetter AG
Graeterstrasse 2
71642 Ludwigsburg | Germany

Phone +49 7141 2550-0
Fax +49 7141 2550-425
info@jetter.de
www.jetter.de

We automate your success.