ISO-Designer

Version Update from V. 5.2.1 to V. 5.2.2

We automate your success

Jetter AG
Graeterstrasse 2
71642 Ludwigsburg, Germany

Phone:

Headquarters	+49 7141 2550-0
Sales	+49 7141 2550-531
Technical hotline	+49 7141 2550-444

E-mail:

Hotline	hotline@jetter
Sales	vertrieb@jetter

Revision 1.00

9/7/2017

This document has been compiled by Jetter AG with due diligence based on the state of the art as known to them. Any revisions and technical advancements of our products are not automatically made available in a revised document. Jetter AG shall not be liable for any errors either in form or content, or for any missing updates, as well as for any damage or detriment resulting from such failure.

Table of Contents

.....2
1 Fixed software bugs.....1
1.1 General issues.....1
1.1.1 Drag&Drop of objects in a container resulted in loss of data.....1

1 Fixed software bugs

This chapter describes the software bugs which have been fixed in the new software release.

1.1 General issues

1.1.1 Drag&Drop of objects in a container resulted in loss of data

Adding images from the file system to a container (group, button, etc.) which was opened in the component editor using drag & drop resulted in a loss of the whole container data.
The same happened if any object from another object pool was added to a container using drag & drop.