



**JetControl 647**  
**Version Update**  
**V. 3.52 to V. 3.53**



Jetter AG reserves the right to make alterations to its products in the interest of technical progress. These alterations need not to be documented in every single case.

This manual and the information contained herein have been compiled with due diligence. Jetter AG shall not be liable for printing errors contained herein or for other consequential damage.

The brand names and product names used in this manual are trade marks or registered trade marks of the respective title owner.

## **Table of Contents**

# 1 Introduction

**2**

<b>Version Updates - Survey</b>			
<b>Version</b>	<b>Function</b>	<b>upgraded</b>	<b>corrected</b>
V 3.53	Error regarding mini-os Optimizing the TCP/IP stack	✓	✓

## **3 Eliminated Software Bugs**

### **3.1 Error Regarding the Mini OS with Delay Register 63892**

In version 3.52, there has been an error, which will only manifest, if the start delay value is unequal ZERO (register 63892).

## **4 New Features:**

### **4.1 Optimizing the TCP/IP Stack**

The IP stack has been optimized in this new version; now, more telegrams can be processed per time unit.