JX2-PROFI1

Versions Update

from V1.01 to V1.03

Jetter

JETTER AG reserves the right to make alterations to its products in the interest of technical progress. These alterations need not be documented in every single case.

This manual and the information contained herein have been compiled with due diligence. However, Jetter AG assumes no liability for printing or other errors or damages arising from such errors.

The brand names and product names used in this document are trademarks or registered trademarks of the respective title owner.

Contents

1 Introduction

Overview of Version Update			
Version	**Function**	**expanded**	**corrected**
V1.03	Acyclic Services		✓
V1.02	Acyclic Services		✓

2 Eliminated Software Bugs

2.1 Acyclic Services

2.1.1 Version 1.02

The module sends with the commands 13 and 14 only the status to the master. The data is not replied.

2.1.2 Version 1.03

The order of the bytes within a word (register) was changed (low byte and high byte).