

JetControl 24x

Version Update

from V3.11 to V3.12

Jetter

Revision 1.00

June 02, 2003 / Printed in Germany

JETTER AG reserves the right to make alterations to its products in the interest of technical progress. These alterations need not be documented in every single case.

This manual and the information contained herein have been compiled with due diligence. However, JETTER AG assumes no liability for printing or other errors or damages arising from such errors.

The brand names and product names used in this document are trademarks or registered trademarks of the respective title owner.

Table of Contents

1 Introduction 4

2 Eliminated Software Bugs 5

2.1 Interpreter 5

1 Introduction

Overview of Version Updates			
Version	**Function**	**Enhanced**	**Corrected**
V3.01	Application program	✓	
	pcom7/JetIP server		✓
	Interpreter		✓
	Hardware	✓	
V3.11	E-Mail	✓	
	HTTP server	✓	✓
	FTP server	✓	
	System bus	✓	✓
	System configuration	✓	
	File system		✓
	Interpreter	✓	✓
	Registers	✓	
	I/O system	✓	
V3.12	Interpreter		✓

2 Eliminated Software Bugs

2.1 Interpreter

Before this version it was not possible from within the application program to directly access inputs and outputs located on expansion modules starting from # 17 (inputs/outputs 1701 through 2416). A program containing I/O numbers within this range was stopped and in the error register 2008 bit 5 ("illegal OP code in the application program") was set.

However, inputs/ouputs on such modules were accessed correctly as long as they were accessed through indirect addressing via a pointer register, overlaid registers (4xxx), through one of the serial interfaces or Ethernet and from within an e-mail or an HTML page.