



JetControl 647
Version Update
V 3.51 to V 3.52



Jetter AG reserves the right to make alterations to its products in the interest of technical progress. These alterations need not to be documented in every single case.

This manual and the information contained herein have been compiled with due diligence. Jetter AG shall not be liable for printing errors contained herein or for other consequential damage.

The brand names and product names used in this manual are trade marks or registered trade marks of the respective title owner.

Table of Contents

1	Introduction	4
2	Eliminated Software Bugs	5
2.1	JetWay Errors during Boot-Up	5
3	Documentation Update	6
4	New Features:	7
4.1	Mini-OS	7

1 Introduction

Version Updates - Survey			
Version	Function	upgraded	corrected
V 3.52	Operating system (JetWay)		✓

2 Eliminated Software Bugs

2.1 JetWay Errors during Boot-Up

In version 3.51, there has been an error which does not manifest often:
In version 3.51, the red LED (ERR1) will occasionally light up during boot-up. This error will only occur during boot-up.

3 Documentation Update

There have been no updates to this edition.

4 New Features:

4.1 Mini-OS

Transmitting a mini operating system by means of the Ethernet will be possible as of this version.

The mini-os grants there is always an Ethernet functionality available, even if an os-update being carried out via Ethernet has been interrupted (the control is switched off during the update).