



JX6-SB
Version Update
from V. 2.18 to V. 2.19



Jetter AG reserve the right to make alterations to their products in the interest of technical progress. These alterations need not be documented in every single case.

This manual and the information contained herein have been compiled with due diligence. However, Jetter AG assume no liability for printing or other errors or damages arising from such errors.

The brand names and product names used in this document are trademarks or registered trademarks of the respective title owner.

Table of Contents

1	Introduction	4
2	Fixed Software Bugs	5
2.1	Operating System Update	5
2.2	Register Access to JetMove at MC	5

1 Introduction

Overview of Version Updates			
Version	Function	Added	Fixed
V 2.19	<i>An os-update to version 2.18 of versions 2.11 and earlier is supported from now on.</i>		X
	<i>Register Access to JetMove at MC</i>		X
V 2.18	<i>Special Registers</i>		
	2000 : Software Version	✓	
	2008 : Error Messages	✓	
	2039 : Peripheral fault	✓	
	<i>Expansion Modules</i>		
	JX3 Modules	✓	
	LioN-S Modules	✓	
	Compactbox Modules LJX7-CSL	✓	
	Milan Drive Advanced MDA	✓	
	JM-105	✓	
	BWU1821, AS interface CANopen gateway	✓	
	<i>Register Access</i>		
	WAGO 750, special terminal, > 7 byte		✓
	JX-SIO analog values and error behavior		✓
	<i>Configuring the System Bus</i>		
	Lenze FU, I/O total		✓
	maxon EPOS, node IDs		✓
V 2.16	<i>Expansion Modules</i>	✓	
	WAGO I/O 750		
	<i>Intelligent JX2 Slave Modules</i>		✓
	Operating system update		
	<i>New Initialization of the System Bus</i>	✓	
	Resetting the digital I/O		
	<i>Configuring to JX6-CON-MOVE</i>		✓
	Compatible as of V. 3.023		
	<i>Command 33</i>		✓
	Storing the default values		

