



# **JX2-SM1D**

Version Update

Version 1.06 to Version 1.07



Jetter AG reserves the right to make alterations to its products in the interest of technical progress. These alterations need not to be documented in every single case.

This user information and the information contained herein have been compiled with due diligence. Jetter AG shall not be liable for errors contained herein or for incidental or consequential damage in connection with the furnishing, performance, or use of this material.

The brand names and product names used in this manual are trade marks or registered trade marks of the respective title owner.

## Table of Contents

<b>1</b>	<b>Introduction</b>	<b>4</b>
<b>2</b>	<b>Expansions</b>	<b>5</b>
<b>3</b>	<b>Eliminated Software Bugs</b>	<b>6</b>
3.1	Endless Run	6

# 1 Introduction

Version Updates - Survey			
Version	Function	upgraded	corrected
V 1.07	Endless run stops unexpectedly		✓

## **2 Expansions**

## 3 Eliminated Software Bugs

### 3.1 Endless Run

#### **Endless run stops unexpectedly**

Any endless run (started by command 56 or 57), would in fact not be endless but stop by itself after 4,294,967,265 steps.

This was due to a firmware error, which has been fixed in version 1.07.