



JetControl 24x
Version Update
from V. 3.16 to V. 3.17



Jetter AG reserves the right to make alterations to its products in the interest of technical progress. These alterations need not to be documented in every single case.

This user information and the information contained herein have been compiled with due diligence. Jetter AG shall not be liable for errors contained herein or for incidental or consequential damage in connection with the furnishing, performance, or use of this material.

The brand names and product names used in this manual are trade marks or registered trade marks of the respective title owner.

Table of Contents

1	Introduction	4
2	Expansions	5
3	Eliminated Software Bugs	6
3.1	System Functions	6

1 Introduction

Version Updates - Survey			
Version	Function	upgraded	corrected
V. 3.17	Interpreter		✓
V. 3.16	Interpreter	✓	✓
V. 3.15	Communication	✓	✓
	Registers	✓	
	Interpreter		✓
	System bus	✓	✓
	E-mail	✓	

2 Expansions

3 Eliminated Software Bugs

3.1 System Functions

In version 3.15 and 3.16 of the operating system, there was an error which could have an effect on some system functions (special functions). The error related to the following functions:

Group of Functions	Function	Number
Modbus/TCP	Reading / writing into the register	65 / 66
RemoteScan	Configuring RemoteScan	80
Data Files	Store / read data; clear a file	90 .. 96
Network	Permanent entry into the ARP table	120
Strings	Comparing, connecting, copying the strings; turning the register into a string	140 .. 144

Under a fault condition, a wrong register number for the function parameters would be transmitted. Whether the correct register number was transmitted or not depended on the instructions that had been carried out in the application program before calling up the system function. Thus, the way system functions were carried out could not be influenced.