



JXM-IO-E32

Version Update from V1.05.0.00 to V1.06.0.00

Version 1.13

February 2023 / Printed in Germany

This document has been compiled by Jetter AG with due diligence, and based on the known state of the art.

In the case of modifications, further developments or enhancements to products shipped in the past, a revised document will be supplied only if required by law, or deemed appropriate by Jetter AG. Jetter AG shall neither be liable nor responsible for any errors in form or content, lacks in updating and possibly resulting damages or disadvantages.

The logos, brand names, and product names mentioned in this document are trademarks of Jetter AG, of associated companies or other title owners and must not be used without consent of the respective title owner.

Table of contents

1	Changes to 1.06.0.00	4
----------	-----------------------------	----------

1 Changes to 1.06.0.00

Overview

Version 1.06.0.00

The following table gives an overview of newly added or enhanced features and fixed software bugs since Version **1.05.0.00**:

Funktion	New	Enhanced	Fixed
It was not possible to map I_TEMPERATURE as a 32-bit value to a PDO. This has been fixed and the user manual has been adjusted accordingly.			✓

Jetter AG
Gräterstraße 2
71642 Ludwigsburg | Germany

Tel +49 7141 2550-0
Fax +49 7141 2550-425
info@jetter.de
www.jetter.de

We automate your success.